



Western Michigan University  
ScholarWorks at WMU

---

Legacy Scout Tickets from Pure Oil Company

---

8-20-2021

**MGRRE\_PureOilScoutTickets\_Figge, Fred\_10\_21121002760000**

MGRRE

*Western Michigan University*

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

---

#### WMU ScholarWorks Citation

MGRRE, "MGRRE\_PureOilScoutTickets\_Figge, Fred\_10\_21121002760000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 7031.

<https://scholarworks.wmich.edu/pure/7031>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



---

**MGRRE\_PureOilScoutTickets\_Figge, Fred\_10\_21121002760000**

API 21121002760000

Permit Number 276

Lease Name Figge, Fred

Well Number 10

County Muskegon

Township 10N

Range 16W

Section 9

2021 DEQ or Pure co\_name Dixie Oil Company

Pure Number 168

Latitude 43.26759

Longitude -86.21959

# Corrected Location Report

168

THE PURE OIL COMPANY

DATE 1-19-29

## LOCATION REPORT

No.

STATE Mich COUNTY Muskegon DIST. TWP. Muskegon SEC. 9 TOWN 10 N RANGE 16 W

WELL No. 10 (SERIAL No. 168) FARM Fred Figg ACRES

NAME OF STREAM OR WATERS QUADRANGLE

OPERATOR Dixie Oil Co MAP

Feet from North Line of Farm

" " East " " "

" " South " " "

" " West " " "

Feet from North Line of Section

" " East " " "

" " South " " "

" " West " " "

### LEGEND

O LOCATION

① RIG

⊕ DRILLING

⊗ GAS WELL

● OIL WELL

⬮ SMALL OIL WELL

⊗ DRY HOLE

⬮ DRY SHOWING OIL

⊗ DRY SHOWING GAS

⬮ ABANDONED LOCATION

⊗ ABANDONED GAS WELL

⬮ ABANDONED OIL WELL

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location. Make copy to keep for reference and send original to Columbus office.

SEE PLAT FOR CORRECTED  
LOCATION OF WELL # 166

N

REMARKS:

SIGNED

Superintendent or Foreman.




STATE MICHIGAN COUNTY MUSKEGON DIST. MUSKEGON SEC. 8 TOWN 10 N RANGE 16 W  
WELL No. 10 (SERIAL No. 168) FARM FRED F. 99E ACRES  
NAME OF STREAM OR WATERS QUADRANGLE NE COR. 4W-16E-SEC. 8  
OPERATOR DIXIE OIL CO. MAP MUSKEGON

Feet from North Line of Farm  
250 " " East " " "  
250 " " South " " "  
" " West " " "  
Feet from North Line of Section  
1070  
1570 " " East " " "  
" " South " " "  
" " West " " "

- LEGEND**
- |                  |                      |
|------------------|----------------------|
| ○ LOCATION       | ✦ DRY HOLE           |
| ① RIG            | ✦ DRY SHOWING OIL    |
| ⊕ DRILLING       | ✦ DRY SHOWING GAS    |
| ⊗ GAS WELL       | ⊗ ABANDONED LOCATION |
| ● OIL WELL       | ⊗ ABANDONED GAS WELL |
| ⬮ SMALL OIL WELL | ⬮ ABANDONED OIL WELL |

NOTE: Below make tracing from map (when no map is obtainable make sketch), showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location. Make copy to keep for reference and send original to Columbus office.



REMARKS:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
SIGNED \_\_\_\_\_  
Superintendent or Foreman.




STATE MICHIGAN COUNTY MUSKEGON DIST TWP. MUSKEGON SEC. 8 TOWN 10-N RANGE 16-W.  
WELL No. TEN (10) (SERIAL No. 168.) FARM FRED FIGGE. 40 ACRES  
NAME OF STREAM OR WATERS QUADRANGLE NE cor. NW NE sec. 8  
OPERATOR DIXIE OIL CO. INC. MAP MUSKEGON AREA.

Feet from North Line of Farm  
250 " " East " " "  
250 " " South " " "  
" " West " " "  
1070 Feet from North Line of Section  
1570 " " East " " "  
" " South " " "  
" " West " " "

- LEGEND**
- |                  |                      |
|------------------|----------------------|
| ○ LOCATION       | ⬮ DRY HOLE           |
| ① RIG            | ⬮ DRY SHOWING OIL    |
| ⊕ DRILLING       | ⬮ DRY SHOWING GAS    |
| ⊗ GAS WELL       | ⬮ ABANDONED LOCATION |
| ● OIL WELL       | ⬮ ABANDONED GAS WELL |
| ⬮ SMALL OIL WELL | ⬮ ABANDONED OIL WELL |

NOTE: Below make tracing from map (when no map is obtainable make sketch), showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location. Make copy to keep for reference and send original to Columbus office.



REMARKS:

SIGNED

Superintendent or Foreman.







**SUPT. OR FOREMAN**